

Figure 1




FIGURE 2




FIGURE 3a




FIGURE 36





FIGURE 4



Digital representation of the above analog signols inverted

Vpv Power-up calibration point/compensation
V2 Point where AUTO Compensation is halted
V4 Point where the rail is out of the field
V3 Point where the rail is detected
V1 Point when the sensor has fallen off the rail
V4-V3 = the hysteresis

Figure 5